

## EPA Warning Signs

Floor stickers are used to define and indicate the limits of an EPA.

Floor Stickers		
Item No.	Size in mm	Language
1603891	120 x 60	English



IEC 61340-5-1 requires that grounding points are clearly designated. This can be done with EBP (Earth bonding Point) and EGP (Earth grounding Point) labels.

- made of strong, self-adhesive vinyl
- yellow, with black print
- 12 mm hole for fitting the label over a press stud connector

EBP labels	
Item No.	Description
1600905	Earth Bonding Point
1600906	Earth Grounding Point



## EPA Warning Signs

According to IEC 61340-5-1 the EPA has to be identified as such.

- made of yellow "foamex"
- treated with a low charging coating
- printed in black to IEC 61340-5-1
- radiused corners with holes for fixing

### EPA warning sign

Item No.	Size in mm	Language
1601732	300 x 150	English
1600893	300 x 150	Dutch



It is crucial to really identify when you are leaving an EPA.

- help raise awareness of the EPA
- conforms to EN 61340-5-2 §4.3
- an aid to both visitors and employees

### EPA Exit warning sign

Item No.	Size in mm	Language
1603173	300 x 150	English

